

Inspection Report

Report No.: XYF-130808
Supplier : XY-GLOBAL

Inspection Date: 2th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYK-130808 Item No.200-40-130	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-40-130	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

6. inspection reports

