



XY Electronics Technology Co., Ltd

## Inspection Report

Report No.: XYK-131014

Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> Nov-, 2013

Inspector: ALEX

|                                                                 |                                   |
|-----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYK-131014    Item No. XY-CT-D-046 | <u>Inspection Result:</u><br>PASS |
|-----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size     | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| XY-CT-D-046 | 20000PCS      | 0.1% inspection | 0pcs         | No failure          | 20000pcs        |

### Appearance Inspection :

No failure,

### Dimension Inspection:

No failure , below measurement report for reference.

### Assembly Test:

No failure


### Inspection Summary

The inspection sample plan is 100% inspection.

### Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]