

Inspection Report

Report No.: XYS-130831
Supplier : XY-GLOBAL

Inspection Date: 11th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYS-130831 Item No. Fishing gear wheel	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Fishing gear wheel	30PCS	100% inspection	30pcs	No failure	30pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]