

Inspection Report

Report No.: XYLA-140316
Supplier : XY-GLOBAL

Inspection Date: 8th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYLA-140316 Item No. 1430021	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1430021	25000PCS	1% inspection	0pcs	No failure	25000PCS

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:



6. Product:

[illegible]