XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYSK-140516 **Inspection Date:** 18th Jun, 2014
Supplier : **XY-GLOBAL** **Inspector:** Leo

Inspection only for:	**Inspection Result:**
PO . XYSK-140516 Item No. XY11WD017	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:



6. Dimensions report

[illegible]	[illegible]
[illegible]	[illegible] ADC12[illegible] A380 [illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	CNC [illegible].
[illegible]	[illegible]
[illegible]	[illegible]
[illegible] / [illegible]	+/- 0.01MM
[illegible]	T / T 50[illegible] 50 [illegible] t / t [illegible].
[illegible]	CNC [illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	20-25 [illegible] t / t 50[illegible] [illegible]
[illegible]	[illegible]
1.Name: [illegible]	
2.Process: [illegible]	
3. [illegible] :[illegible] ADC12[illegible] a380 [illegible]	
4. [illegible] :[illegible]	
5. [illegible] 0.01 -/+ [illegible] :[illegible]	
6. [illegible] [illegible]100 :[illegible]	
7. [illegible] :[illegible]	
8. [illegible] 30-25 :[illegible].	
9. [illegible] :[illegible].	
10. [illegible] :[illegible].	
11. 9001 [illegible] :[illegible]	
[illegible]	
1. 10 [illegible]	
2. [illegible]	
3. [illegible]	
4. [illegible]	
5. [illegible]	
6. [illegible]	
7. [illegible]	
[illegible]	
[illegible] :[illegible]	
[illegible] :[illegible]	
[illegible]: iso9001	
[illegible] :[illegible]	
[illegible]	

[illegible]