

Inspection Report

Report No.: XYS-130723
Supplier: XY-GLOBAL

Inspection Date: 12th Jun-, 2014
Inspector: LEO

Inspection only for: PO : XYS-130723 Item No. Aluminum cylinder units	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Aluminum cylinder units	100PCS	50pcs inspection	0pcs	No failure	100pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]