

## Inspection Report

**Report No.:** XYDA-150310

**Supplier :** XY-GLOBAL

**Inspection Date:** 4<sup>th</sup> Apr, 2015

**Inspector: Leo**

|                                                                  |                                   |
|------------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYDA-150310      Item No. XY31CY028 | <u>Inspection Result:</u><br>PASS |
|------------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY31CY028   | 30000PCS      | 1% inspection | Opes         | No failure          | 30000pcs        |

**Appearance Inspection :**

No failure.

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

## Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



## 1. Packing



## 2. Product



## 3. Product



## 4 Product



## 5. Product:

## 6. report

[illegible]