

Inspection Report



Report No.: XYJ-140315
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYJ-140315 Item No. 2480112	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2480112	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4. Product
	
5. Product:	6. Product:

[illegible]