

Inspection Report

Report No.: XYL-150725

Inspection Date:14th Sep, 2015

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYZ-150725 Item No. XY11LM025	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM025	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. Report:

[illegible]

High qualified surface treatment can make your parts perfect !!!

