XY-GLOBAL **XY Electronics Technology Co., Ltd**

Inspection Report

Report No.: XYL-150716
Supplier : **XY-GLOBAL**

Inspection Date: 27th Aug, 2015
Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYL-150716 Item No. XY11LM016	**PASS**

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM016	**7000PCS**	1% inspection	0pcs	No failure	7000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. Report:

□□□□□□□□□	□□□□□□□□ □□□□□□□□□ □□□□□□□ □□□□□□ □□□□□□□□□ □□□□□□□ □□□□ □□□□ □□□□□ □□□□ □□□□□□□ □□□□□□□ □□□□□ □□□□□ □□□□□□□□□ □□□□ □□□□ □□□□ □□□□□ □□□□□□ □□□□□ □□□□ □□□□□ □□□□□□□□□□ □□□□ □□□□ □□□□
□□□□□□□	□□□□□□□□□□ ADC12□ A380 □□□
□□□□□□□□	□□□□□□ □□□□ □□□ □□□□□□□
□□□□□□□□ □□□□□□□□	□□□□□□ □□□□□□□□□□ □□□□□□□ □□□□□□□□ □□□□□□□ □□□□□□ □□□□□□□ □□□□□□□ □□□□□ □□□ □□□□ □□□□□□
□□□	□□□□□□ □□□□□□□□ □□□□ □□ □□□□□ □□□□
□□□□□□□□ □□□□□	□□□□□□ □□□ □□□□ □□□ □□□□ □□□ □□□□□□□ □□□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□ □□□ □□□ □□□□□ □□□□□□ □□□□□□□□ □□□□□□□ □□□□□□ □□□ □□□□□□ □□□□□ □□□
□□□□ □□□□□	□□□□□□□□ □□□□□□ □□□□□□□ □□□□□ gague□ □□□□□□□□ □□□□ □□□□□□□ □□□□□ □□□□□□□ □□□□ □□□□□□□□□ □□□□ □□□□□□□□ □□□□□□□ □□□□□□□ □□□□□□□ □□□□□ □□□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□ □□□□□ □□□
□□□	□□□□□□□ □□□□
□□□□□□□ / □□□□□	+/- 0.01MM
□□□	T / T 50 □ □□□□□ □50 □□□□□□ T / T □□□□□ □□ □□□□□□ □□□.
□□□□□□□ □□□□	□□□□□□□ □□□□□ □□□□□□□□□ □□□□□□□ □□□□ □□□□□ □□□□□ □□□□□□□□ □□□□□□□ □□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□□□□ □□□□□□□ □□□□□ □□□□□ □□□□□ □□□□□□□□ □□□ □□□□□□ □□□□□ □□□□
□□□□□	□□□□□□□□ □□□□□□□□□□ □□□□□□□□ □□□□ □□□□□□□ □□□□□□□□ □□□□ □□□□□ □□□□ □□□□ □□□□□ □□□□ □□□□ □□□□□□□□□□ □□□□□□□□□□ □□ □□□□□□ □□□□□□□□□□□ □□□□□□□□
□□□□□□□	□□□□□ □□□□□
□□□□□ □□□□	20-25 □□□ □□□□ T / T 50□ □□□□□□□ □□
□□□□□□□□ □□□□□□□	□□□□□□□□□ □□□□□□ □□□□
1.Name: □□□□□ □□□□ □□□□ □□□□□□□□□□ □□□□□□□ □□□□□□□ □□□□□ □□□□ □□□□□
2.Process: □□□□□ □□□□□□ □□□□□□□□ □□□□□□ □□□□□□ □□□□□ □□□□ □□□□□□□□□□
3.Material: □□□□□□□□□□ □□ ADC12□ A380 □□□
4.Surface □□□□□□ □□□□□□□ □□□□□□ □□□□□□□ □□□□□□□ □□□□□□□□ □□□□□ □□□□□□ :□□□□□
5.Tolerance: 0.01 -/+ □□□ □□□ □□ □□□□MM
6.Quality □□□□□□□ □100 :□□□□□□
7.Specification: OEM □□□□□□ □□□□□ □□ □□□□ □□□□□
8. □□□□□□□□ □□ □□□□□ 30-25 :□□□□□□□ □□□ □□□□.
9. □□□□□□□ □□□□□□□□ □□□□□□□□□□□ □□□□ □□□□ □□□□□□□□□□ □□□ :□□□□□ accessoried □□□□ □□□□ □□□ □□□□□□□□
10. □□□□ □□□□□□□□□□ □□□□□□□ □□□□□□□□ :□□□□□□□□ AUSTRIAL□ □□□□□□ □□□□□□□□ □□□□□□□
11. □□□□□: ISO 9001
□□□□ □□□□□
1. 10 □□□□□□ □□□□□ □□ □□□□□□ □□ □□□□
2. □□□□□ □□□□□□ □□□□□ □□□□
3. □□ kindls □□ finishment □□ □□□□□□□□ abailable
4. □□□□□□□ □□□□□□ □□□□□ □□□□ □□□
5. □□□□ □□□□□□ □□□□□ □□ □□□□□□□
6. □□□□□ □□□□
7. □□□□□□ □□□□□ □□□□ □□□ □□□□□□□ □□ □□□□ □□□□ □□
□□□□□□□
□□□□□□□ □□□□□ □□□□ :□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□
□□□□□□□□ □□□□□□□ :□□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□
□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□: ISO9001
□□□□ □□□□□□ □□□□□□ :□□□□□□ □□□□□ □□□□ □□□□ □□□□□□□□□
□□□□□ □□□□ □□□□ □□□□□□□□□ OEM □□□□□ □□□□ □□

Safety is our serious job for our worker and engineer team