

Inspection Report

Report No.: XYBA-141119

Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYBA-141119 Item No. XY21ZC038	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC038	5000Set	7% inspection	0pcs	No failure	6000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

[illegible]

6. Inspection report:

[illegible]