

Inspection Report

Report No.: XYSS-131010

Supplier: XY-GLOBAL

Inspection Date: 25th Nov., 2013

Inspector: LEO

Inspection only for: PO . XYSS-131010 Item No. Cylinder_FirstAid	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Cylinder_FirstAid	6PCS	100% inspection	0pcs	No failure	6pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]