

Inspection Report

Report No.: XYKB-140522

Supplier : XY-GLOBAL

Inspection Date: 15th- Jun, 2014

Inspector: Leo

Inspection only for: PO . XYKB-140522 Item No. XY72YM018	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM018	1000PCS	1% inspection	Opes	No failure	1000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. Dimensions report:

[illegible]