

Inspection Report

Report No.: XYSL-130506

Supplier : XY-GLOBAL

Inspection Date: 8th Jun, 2013

Inspector: Leo

Inspection only for: PO . XYSL-130506 Item No. XY11SL003	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL003	2000PCS	5% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure	
------------	--

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

[illegible]

6. The test report

[illegible]