

Inspection Date: 5th Sep, 2015
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM020	11000PCS	1% inspection	Opes	No failure	11000pcs

The inspection sample plan is 100% inspection.

A large stack of cardboard boxes, secured with straps, on a wooden pallet. The boxes are arranged in a neat, rectangular stack, and the straps are visible across the front and sides. The pallet is made of wooden slats. The background shows a concrete floor and a wall.



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. Report:

[illegible]

Safety is our serious job for our worker and engineer team

