

Inspection Report

Report No.: XYSK-140609

Supplier : XY-GLOBAL

Inspection Date: 2th July, 2014

Inspector: Leo

Inspection only for: PO : XYSK-140609 Item No. XY31SY009	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY009	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Report

Product Name: XY31SY009 Inspection Date: 2014-07-02 Inspected By: Leo

PO: XYSK-140609 Item No: XY31SY009 Qty: 8000PCS Defect: 0PCS Pass: 8000PCS

Inspection Result: PASS

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Details:

Item	Specification	Inspection Result
1. Appearance	1.1. No visible defects	Pass
2. Dimension	2.1. No visible defects	Pass
3. Assembly	3.1. No visible defects	Pass
4. Test	4.1. No visible defects	Pass

Inspector: Leo Date: 2014-07-02

5. Product:

6. report

[illegible]