

Inspection Report

Report No.: XYSL-150609

Inspection Date: 15th July, 2015

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO : XYSL-150609 Item No. XY31XL007	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL007	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

pocdmis		400011008		11.0.0.001		10.0	
E.C.S.		10.0		10.0		10.0	
1		10.0		10.0		10.0	
2		10.0		10.0		10.0	
3		10.0		10.0		10.0	
4		10.0		10.0		10.0	
5		10.0		10.0		10.0	
6		10.0		10.0		10.0	
7		10.0		10.0		10.0	
8		10.0		10.0		10.0	
9		10.0		10.0		10.0	
10		10.0		10.0		10.0	
11		10.0		10.0		10.0	
12		10.0		10.0		10.0	
13		10.0		10.0		10.0	
14		10.0		10.0		10.0	
15		10.0		10.0		10.0	
16		10.0		10.0		10.0	
17		10.0		10.0		10.0	
18		10.0		10.0		10.0	
19		10.0		10.0		10.0	
20		10.0		10.0		10.0	
21		10.0		10.0		10.0	
22		10.0		10.0		10.0	
23		10.0		10.0		10.0	
24		10.0		10.0		10.0	
25		10.0		10.0		10.0	
26		10.0		10.0		10.0	
27		10.0		10.0		10.0	
28		10.0		10.0		10.0	
29		10.0		10.0		10.0	
30		10.0		10.0		10.0	
31		10.0		10.0		10.0	
32		10.0		10.0		10.0	
33		10.0		10.0		10.0	
34		10.0		10.0		10.0	
35		10.0		10.0		10.0	
36		10.0		10.0		10.0	
37		10.0		10.0		10.0	
38		10.0		10.0		10.0	
39		10.0		10.0		10.0	
40		10.0		10.0		10.0	
41		10.0		10.0		10.0	
42		10.0		10.0		10.0	
43		10.0		10.0		10.0	
44		10.0		10.0		10.0	
45		10.0		10.0		10.0	
46		10.0		10.0		10.0	
47		10.0		10.0		10.0	
48		10.0		10.0		10.0	
49		10.0		10.0		10.0	
50		10.0		10.0		10.0	
51		10.0		10.0		10.0	
52		10.0		10.0		10.0	
53		10.0		10.0		10.0	
54		10.0		10.0		10.0	
55		10.0		10.0		10.0	
56		10.0		10.0		10.0	
57		10.0		10.0		10.0	
58		10.0		10.0		10.0	
59		10.0		10.0		10.0	
60		10.0		10.0		10.0	
61		10.0		10.0		10.0	
62		10.0		10.0		10.0	
63		10.0		10.0		10.0	
64		10.0		10.0		10.0	
65		10.0		10.0		10.0	
66		10.0		10.0		10.0	
67		10.0		10.0		10.0	
68		10.0		10.0		10.0	
69		10.0		10.0		10.0	
70		10.0		10.0		10.0	
71		10.0		10.0		10.0	
72		10.0		10.0		10.0	
73		10.0		10.0		10.0	
74		10.0		10.0		10.0	
75		10.0		10.0		10.0	
76		10.0		10.0		10.0	
77		10.0		10.0		10.0	
78		10.0		10.0		10.0	
79		10.0		10.0		10.0	
80		10.0		10.0		10.0	
81		10.0		10.0		10.0	
82		10.0		10.0		10.0	
83		10.0		10.0		10.0	
84		10.0		10.0		10.0	
85		10.0		10.0		10.0	
86		10.0		10.0		10.0	
87		10.0		10.0		10.0	
88		10.0		10.0		10.0	
89		10.0		10.0		10.0	
90		10.0		10.0		10.0	
91		10.0		10.0		10.0	
92		10.0		10.0		10.0	
93		10.0		10.0		10.0	
94		10.0		10.0		10.0	
95		10.0		10.0		10.0	
96		10.0		10.0		10.0	

[illegible]

本公司 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 : ISO9001 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 承接 各種 機械 加工 業務 OEM

Safety is our serious job for our worker and engineer team

