

Inspection Report

Report No.: XYD-140508
Supplier : XY-GLOBAL

Inspection Date: 6th Jun, 2014
Inspector: Alex

Inspection only for: PO . XYD-140508 Item No.XY-1415249	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1415249	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

The image shows a detailed measurement report table with multiple columns and rows of data, likely generated by a software tool like pcdmis.

6. Report:

[illegible]