

Inspection Report

Report No.: XYSL-150603

Inspection Date: 2th July, 2015

Supplier : XY-GLOBAL

Inspector: Leo

Inspection only for: PO . XYSL-150603 Item No. XY31XL002	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL002	22000PCS	1% inspection	Opcs	No failure	22000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

po:dmis		4000-01-08		4.0.0.0	
		100%	50%	100%	50%
a	100%	100%	100%	100%	100%
1	100%	100%	100%	100%	100%
2	100%	100%	100%	100%	100%
3	100%	100%	100%	100%	100%
4	100%	100%	100%	100%	100%
5	100%	100%	100%	100%	100%
6	100%	100%	100%	100%	100%
7	100%	100%	100%	100%	100%
8	100%	100%	100%	100%	100%
9	100%	100%	100%	100%	100%
10	100%	100%	100%	100%	100%
11	100%	100%	100%	100%	100%
12	100%	100%	100%	100%	100%
13	100%	100%	100%	100%	100%
14	100%	100%	100%	100%	100%
15	100%	100%	100%	100%	100%
16	100%	100%	100%	100%	100%
17	100%	100%	100%	100%	100%
18	100%	100%	100%	100%	100%
19	100%	100%	100%	100%	100%
20	100%	100%	100%	100%	100%
21	100%	100%	100%	100%	100%
22	100%	100%	100%	100%	100%
23	100%	100%	100%	100%	100%
24	100%	100%	100%	100%	100%
25	100%	100%	100%	100%	100%
26	100%	100%	100%	100%	100%
27	100%	100%	100%	100%	100%
28	100%	100%	100%	100%	100%
29	100%	100%	100%	100%	100%
30	100%	100%	100%	100%	100%
31	100%	100%	100%	100%	100%
32	100%	100%	100%	100%	100%
33	100%	100%	100%	100%	100%
34	100%	100%	100%	100%	100%
35	100%	100%	100%	100%	100%
36	100%	100%	100%	100%	100%
37	100%	100%	100%	100%	100%
38	100%	100%	100%	100%	100%
39	100%	100%	100%	100%	100%
40	100%	100%	100%	100%	100%
41	100%	100%	100%	100%	100%
42	100%	100%	100%	100%	100%
43	100%	100%	100%	100%	100%
44	100%	100%	100%	100%	100%
45	100%	100%	100%	100%	100%
46	100%	100%	100%	100%	100%
47	100%	100%	100%	100%	100%
48	100%	100%	100%	100%	100%
49	100%	100%	100%	100%	100%
50	100%	100%	100%	100%	100%
51	100%	100%	100%	100%	100%
52	100%	100%	100%	100%	100%
53	100%	100%	100%	100%	100%
54	100%	100%	100%	100%	100%
55	100%	100%	100%	100%	100%
56	100%	100%	100%	100%	100%
57	100%	100%	100%	100%	100%
58	100%	100%	100%	100%	100%
59	100%	100%	100%	100%	100%
60	100%	100%	100%	100%	100%
61	100%	100%	100%	100%	100%
62	100%	100%	100%	100%	100%
63	100%	100%	100%	100%	100%
64	100%	100%	100%	100%	100%
65	100%	100%	100%	100%	100%
66	100%	100%	100%	100%	100%
67	100%	100%	100%	100%	100%
68	100%	100%	100%	100%	100%
69	100%	100%	100%	100%	100%
70	100%	100%	100%	100%	100%
71	100%	100%	100%	100%	100%
72	100%	100%	100%	100%	100%
73	100%	100%	100%	100%	100%
74	100%	100%	100%	100%	100%
75	100%	100%	100%	100%	100%
76	100%	100%	100%	100%	100%
77	100%	100%	100%	100%	100%
78	100%	100%	100%	100%	100%
79	100%	100%	100%	100%	100%
80	100%	100%	100%	100%	100%
81	100%	100%	100%	100%	100%
82	100%	100%	100%	100%	100%
83	100%	100%	100%	100%	100%
84	100%	100%	100%	100%	100%
85	100%	100%	100%	100%	100%
86	100%	100%	100%	100%	100%
87	100%	100%	100%	100%	100%
88	100%	100%	100%	100%	100%
89	100%	100%	100%	100%	100%
90	100%	100%	100%	100%	100%
91	100%	100%	100%	100%	100%
92	100%	100%	100%	100%	100%
93	100%	100%	100%	100%	100%
94	100%	100%	100%	100%	100%
95	100%	100%	100%	100%	100%
96	100%	100%	100%	100%	100%
97	100%	100%	100%	100%	100%
98	100%	100%	100%	100%	100%
99	100%	100%	100%	100%	100%
100	100%	100%	100%	100%	100%

5. Product:

6. report

[illegible]

Safety is our serious job for our worker and engineer team

