

Inspection Report

Report No.: XYSK-140617

Supplier: XY-GLOBAL

Inspection Date: 10th- July, 2014

Inspector: Leo

Inspection only for: PO . XYSK-140617 Item No. XY31SY017	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY017	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

[illegible]