

Inspection Report

Report No.: XYL-150722
Supplier: XY-GLOBAL

Inspection Date: 5th Sep, 2015
Inspector: Leo

Inspection only for: PO: XYL-150722 Item No. XY11LM022	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM022	16000PCS	1% inspection	0pcs	No failure	16000pcs

Appearance Inspection:
No failure,
Dimension Inspection:
No failure, below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records:	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

[illegible]

