

Inspection Report

Report No.: XYKB-140511
Supplier: XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140511 Item No. XY72YM007	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM007	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd

Inspection Part	Product Type	Inspection Date	Inspector
XY72YM007	XY72YM007	2014.06.07	Leo
Inspection Item	Inspection Result	Inspection Status	Inspection Remarks
Appearance	OK	OK	OK
Dimension	OK	OK	OK
Assembly	OK	OK	OK
Test	OK	OK	OK
Storage	OK	OK	OK
Transportation	OK	OK	OK
Usage	OK	OK	OK
Disposal	OK	OK	OK
Recycling	OK	OK	OK
Other	OK	OK	OK

6. Dimensions report:

[illegible]