

Inspection Report

Report No.: XYSL-150619
Supplier : XY-GLOBAL

Inspection Date: 25th July, 2015
Inspector: Leo

Inspection only for: PO : XYSL-150619 Item No. XY31XL017	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

pocdmis		M02-01-108		J. B. 015	
Date		Time		Page	
1. 01-01		01-01		01-01	
2. 01-01		01-01		01-01	
3. 01-01		01-01		01-01	
4. 01-01		01-01		01-01	
5. 01-01		01-01		01-01	
6. 01-01		01-01		01-01	
7. 01-01		01-01		01-01	
8. 01-01		01-01		01-01	
9. 01-01		01-01		01-01	
10. 01-01		01-01		01-01	
11. 01-01		01-01		01-01	
12. 01-01		01-01		01-01	
13. 01-01		01-01		01-01	
14. 01-01		01-01		01-01	
15. 01-01		01-01		01-01	
16. 01-01		01-01		01-01	
17. 01-01		01-01		01-01	
18. 01-01		01-01		01-01	
19. 01-01		01-01		01-01	
20. 01-01		01-01		01-01	
21. 01-01		01-01		01-01	
22. 01-01		01-01		01-01	
23. 01-01		01-01		01-01	
24. 01-01		01-01		01-01	
25. 01-01		01-01		01-01	
26. 01-01		01-01		01-01	
27. 01-01		01-01		01-01	
28. 01-01		01-01		01-01	
29. 01-01		01-01		01-01	
30. 01-01		01-01		01-01	
31. 01-01		01-01		01-01	
32. 01-01		01-01		01-01	
33. 01-01		01-01		01-01	
34. 01-01		01-01		01-01	
35. 01-01		01-01		01-01	
36. 01-01		01-01		01-01	
37. 01-01		01-01		01-01	
38. 01-01		01-01		01-01	
39. 01-01		01-01		01-01	
40. 01-01		01-01		01-01	
41. 01-01		01-01		01-01	
42. 01-01		01-01		01-01	
43. 01-01		01-01		01-01	
44. 01-01		01-01		01-01	
45. 01-01		01-01		01-01	
46. 01-01		01-01		01-01	
47. 01-01		01-01		01-01	
48. 01-01		01-01		01-01	
49. 01-01		01-01		01-01	
50. 01-01		01-01		01-01	
51. 01-01		01-01		01-01	
52. 01-01		01-01		01-01	
53. 01-01		01-01		01-01	
54. 01-01		01-01		01-01	
55. 01-01		01-01		01-01	
56. 01-01		01-01		01-01	
57. 01-01		01-01		01-01	
58. 01-01		01-01		01-01	
59. 01-01		01-01		01-01	
60. 01-01		01-01		01-01	
61. 01-01		01-01		01-01	
62. 01-01		01-01		01-01	
63. 01-01		01-01		01-01	
64. 01-01		01-01		01-01	
65. 01-01		01-01		01-01	
66. 01-01		01-01		01-01	
67. 01-01		01-01		01-01	
68. 01-01		01-01		01-01	
69. 01-01		01-01		01-01	
70. 01-01		01-01		01-01	
71. 01-01		01-01		01-01	
72. 01-01		01-01		01-01	
73. 01-01		01-01		01-01	
74. 01-01		01-01		01-01	
75. 01-01		01-01		01-01	
76. 01-01		01-01		01-01	
77. 01-01		01-01		01-01	
78. 01-01		01-01		01-01	
79. 01-01		01-01		01-01	
80. 01-01		01-01		01-01	
81. 01-01		01-01		01-01	
82. 01-01		01-01		01-01	
83. 01-01		01-01		01-01	
84. 01-01		01-01		01-01	
85. 01-01		01-01		01-01	
86. 01-01		01-01		01-01	
87. 01-01		01-01		01-01	
88. 01-01		01-01		01-01	
89. 01-01		01-01		01-01	
90. 01-01		01-01		01-01	
91. 01-01		01-01		01-01	
92. 01-01		01-01		01-01	
93. 01-01		01-01		01-01	
94. 01-01		01-01		01-01	
95. 01-01		01-01		01-01	
96. 01-01		01-01		01-01	
97. 01-01		01-01		01-01	
98. 01-01		01-01		01-01	
99. 01-01		01-01		01-01	
100. 01-01		01-01		01-01	

6. report

[illegible]

Safety is our serious job for our worker and engineer team



[شركة تصنيع المعدات الأصلية بلاستيكية العفن](#)