

Inspection Report

Report No.: XYA-130205
Supplier : XY-GLOBAL

Inspection Date: 24th Apr., 2013
Inspector:KEN

Inspection only for:	Inspection Result:
Item No: CA241-0208	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
CA241-0208	320000 PCS	500PCS	5pcs	No failure, with little flaws, acceptable	320000pcs

Appearance Inspection :
5pcs burrs and scratch on products surface, acceptable
Dimension Inspection:
No failure , refer to measurement report.
Assembly Test:
No failure
Inspection Summary
The inspection sample is 100% inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Packing	4. Packing
	
5. Product	6. Product
	
7. Product	8. Product
	
9. Inspection	10. Inspection
	
11. Inspection	12. Inspection

