

Inspection Report

Report No.: XYCY-150317
Supplier : XY-GLOBAL

Inspection Date: 14th Apr, 2015
Inspector: Leo

Inspection only for: PO : XYCY-150317 Item No. XY31CY019	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY019	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd	
Inspection Report Product Name: XY31CY019 PO: XYCY-150317 Date: 14/04/2015 Inspector: Leo	Inspection Date: 14/04/2015 Inspected By: Leo Approved By: Leo
Inspection Item: 1. Appearance 2. Dimension 3. Function 4. Assembly 5. Packaging 6. Labeling 7. Marking 8. Others	Inspection Result: 1. Appearance: Pass 2. Dimension: Pass 3. Function: Pass 4. Assembly: Pass 5. Packaging: Pass 6. Labeling: Pass 7. Marking: Pass 8. Others: Pass
Inspection Method: 1. Visual Inspection 2. Dimensional Measurement 3. Functional Test 4. Assembly Test 5. Packaging Test 6. Labeling Test 7. Marking Test 8. Others	Inspection Equipment: 1. Caliper 2. Micrometer 3. Gauge 4. Scale 5. Others
Inspection Environment: 1. Temperature: 25°C 2. Humidity: 50% 3. Light: Normal 4. Others	Inspection Conclusion: The inspection results show that the product meets the requirements of the inspection plan. The inspection is passed.
Inspection Report No: XYCY-150317-001	Inspection Report Date: 14/04/2015

5. Product:

6. report

