

Inspection Report

Report No.: XYLA-150301
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYLA-150301 Item No. XY31PC001	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC001	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY31PC001									
Q'ty	30000	30000	30000	30000	30000	30000	30000	30000	30000
Lot No.	150301	150301	150301	150301	150301	150301	150301	150301	150301
Inspection Date	10/04/2015	10/04/2015	10/04/2015	10/04/2015	10/04/2015	10/04/2015	10/04/2015	10/04/2015	10/04/2015
Inspector	Leo	Leo	Leo	Leo	Leo	Leo	Leo	Leo	Leo
Defect Found	0	0	0	0	0	0	0	0	0
Defects Description	No failure	No failure	No failure	No failure	No failure	No failure	No failure	No failure	No failure
Acceptable Q'ty	30000	30000	30000	30000	30000	30000	30000	30000	30000
Inspection Result	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

6. report

[illegible]

Safety is our serious job for our worker and engineer team

