

Inspection Report

Report No.: XYWD-140624
Supplier : XY-GLOBAL

Inspection Date: 20th July, 2014
Inspector: Leo

Inspection only for: PO : XYWD-140624 Item No. XY31SY41	Inspection Result: PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY41	80000PCS	1% inspection	0pcs	No failure	80000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Inspection Date: 2014.07.20	Product Name XY31SY41	Inspector Leo	Customer Name XY-GLOBAL
Inspection Result: PASS			
Inspection Summary: No failure found.			
Inspection Details: 100% inspection.			
Inspection Conclusion: The product meets the requirements.			

5. Product:

6. report

[illegible]