

Inspection Report

Report No.: XYN-140609
Supplier : XY-GLOBAL

Inspection Date: 4th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140609 Item No.190245	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
190245	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product




5. Product:



6. Product::



7. Product:



8. Report:

[illegible]