

Inspection Report


Report No.: XYA-130507
Supplier : XY-GLOBAL

Inspection Date: 12th Jun-, 2013
Inspector: LEO

Inspection only for: PO . XYA-130507 Item No. Spacer	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Spacer	1000PCS	50pcs inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 50pcs inspection.

Digital photo records :	
	
1. Packing	2. Packing
	
3. Product:	4. Product:
	
5. Product :	6. Product:

[illegible]