

Inspection Report

Report No.: XYDA-150317

Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015

Inspector: Leo

Inspection only for:	<u>Inspection Result:</u>
PO . XYDA-150317 Item No. XY31CY034	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY034	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

[illegible]

5. Product:

6. report

[illegible]