



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYZ-130813

Inspection Date: 02nd Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO : XYZ-130813 Item No. 1400320	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400320	3000PCS	1% inspection	0pcs	No failure	3000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

[illegible]