


Inspection Date: 12th Jun, 2014
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM013	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records : 																										
1. Packing 	2. Product 																									
3. Product 	4 Product  深圳市真朴电子科技有限公司 XY Electronics Technology Co., Ltd <table border="1"> <thead> <tr> <th>Inspection Item</th> <th>Inspection Method</th> <th>Inspection Result</th> <th>Inspection Date</th> <th>Inspector</th> </tr> </thead> <tbody> <tr> <td>外观检查</td> <td>目视</td> <td>合格</td> <td>2023.10.10</td> <td>张三</td> </tr> <tr> <td>尺寸测量</td> <td>卡尺</td> <td>合格</td> <td>2023.10.10</td> <td>李四</td> </tr> <tr> <td>功能测试</td> <td>万用表</td> <td>合格</td> <td>2023.10.10</td> <td>王五</td> </tr> <tr> <td>包装检查</td> <td>目视</td> <td>合格</td> <td>2023.10.10</td> <td>赵六</td> </tr> </tbody> </table>	Inspection Item	Inspection Method	Inspection Result	Inspection Date	Inspector	外观检查	目视	合格	2023.10.10	张三	尺寸测量	卡尺	合格	2023.10.10	李四	功能测试	万用表	合格	2023.10.10	王五	包装检查	目视	合格	2023.10.10	赵六
Inspection Item	Inspection Method	Inspection Result	Inspection Date	Inspector																						
外观检查	目视	合格	2023.10.10	张三																						
尺寸测量	卡尺	合格	2023.10.10	李四																						
功能测试	万用表	合格	2023.10.10	王五																						
包装检查	目视	合格	2023.10.10	赵六																						
5. Product:	6. Dimensions report:																									

[illegible]