

Inspection Report

Report No.: XYBA-141122

Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014

Inspector:LEO

Inspection only for:	Inspection Result:
PO : XYBA-141122 Item No. XY21ZC040	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC040	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
用途	工业机械零件
表面处理	阳极氧化
交货期	15天
包装	纸箱
备注	+/-0.01mm
重量	50g/件
长度	50mm
直径	25mm
厚度	5mm

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

[illegible]

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 1000000 ISO

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6. □□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM					
-----	--	--	--	--	--