



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYF-130806

Supplier : XY-GLOBAL

Inspection Date: 2th Sep, 2013

Inspector: LEO

Inspection only for: PO : XYK-130806 Item No. 200-140097	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-140097	20000Set	100% inspection	0pcs	No failure	20000Set

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

The table is a detailed measurement report for part 200-140097. It includes columns for Item No., Lot No., Date, and various dimensions. The data is organized into multiple sections, each corresponding to a different part of the component. The report shows that all dimensions are within the specified tolerance ranges.

6. inspection reports

[illegible]