



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130810

Supplier : XY-GLOBAL

Inspection Date:12th- Sep-, 2013

Inspector:LEO

Inspection only for:	<u>Inspection Result:</u>
PO . XYK-130810 Item No.1300420	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300420	500PCS	3% inspection	0pcs	No failure	500pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing




2. Product:




3. Product:



4. Product:



5. Product :



6. Product:

	CNC
	AL6061 AL6065AL6063AL7075 SUS304SUS303SUS316
	&NBSP;
	gague
	+/-0.01
	T / T 50T / T
	20-25; T / T 50
1.Name CNC	
2.Process	
AL6061 AL6065AL6063AL7075	
4.	
5.Tolerance ±0.01	
6.100	
7.Specification serice	
8.25-30	
9.accessoried	
10.Austrial	
11&NBSP;ISO 9001	
110ISO	
2	
3kindlsavailable	
4	
5	
6	
7	
&NBSP;	
ISO9001	