

AL 6061□□□□



Inspection Report

Report No.: XYK-130816
 Supplier : XY-GLOBAL




Inspection Date:12th Sep-, 2013
 Inspector:LEO

Inspection only for: PO . XYK-130816 Item No.1300430	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300430	500PCS	3% inspection	0pcs	No failure	500pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	铝合金 CNC 加工零件
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
规格	按图
数量	按图
公差	按图
表面处理	阳极氧化
包装	按图
交货期	按图
付款方式	按图
其他要求	按图
1.Name	铝合金 CNC 加工零件
2.Process	铝合金 CNC 加工
3. Material	AL6061 AL6065 AL6063 AL7075
4. Tolerance	按图
5. Tolerance	±0.01
6. Quantity	100
7. Specification	按图
8. Surface Treatment	25-30 阳极氧化
9. Accessories	accessories
10. Certification	Austrial
11. ISO 9001	按图
其他要求	按图
1. ISO 9001	按图
2. ISO 9001	按图
3. ISO 9001	按图
4. ISO 9001	按图
5. ISO 9001	按图
6. ISO 9001	按图
7. ISO 9001	按图
其他要求	按图
按图	按图