

6061□□□□



XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYK-130803

Inspection Date: 06th Sep-, 2013

Supplier : XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYK-130803 Item No.1305970	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300098	2000PCS	3% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure


Inspection Summary

The inspection sample plan is 100% inspection.


Digital photo records :




1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

物料名称	铝棒 CNC 加工
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
数量	10000
单位	米
材质	AL6061
直径	100
长度	1000
公差	±0.01
表面	阳极氧化
包装	木箱
交货	20-25 天
备注	
1.Name	铝棒 CNC 加工
2.Process	铝棒 CNC 加工
3.Specification	AL6061 AL6065 AL6063 AL7075
4.Tolerance	±0.01
5.Surface	阳极氧化
6.Length	1000
7.Diameter	100
8.Quantity	10000
9.Unit	米
10.Material	AL6061
11.Delivery	20-25 天
12.Note	
13.Name	铝棒 CNC 加工
14.Process	铝棒 CNC 加工
15.Specification	AL6061 AL6065 AL6063 AL7075
16.Tolerance	±0.01
17.Surface	阳极氧化
18.Length	1000
19.Diameter	100
20.Quantity	10000
21.Unit	米
22.Material	AL6061
23.Delivery	20-25 天
24.Note	