

Inspection Report

Report No.: XYSK-140523
Supplier : XY-GLOBAL

Inspection Date: 24th Jun, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO : XYSK-140523 Item No. XY11WD022	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD022	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

XY11WD022									
NO	ITEM	UNIT	MIN	MAX	MIN	MAX	MIN	MAX	MIN
1	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
2	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
3	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
4	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
5	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
6	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
7	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
8	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
9	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
10	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
11	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
12	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
13	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
14	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
15	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
16	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
17	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
18	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
19	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
20	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
21	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
22	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
23	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
24	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
25	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
26	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
27	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
28	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
29	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
30	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
31	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
32	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
33	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
34	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
35	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
36	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
37	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
38	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
39	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
40	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
41	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
42	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
43	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
44	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
45	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
46	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
47	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
48	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
49	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00
50	Ø11.0	mm	10.95	11.05	11.00	11.00	11.00	11.00	11.00

6. Dimensions report

[illegible]