

Inspection Report

Report No.: XYLA-150303
Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYLA-150303 Item No. XY31PC002	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC003	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product



5. Product:

Item	Spec	Actual	Unit	Pass	Fail	Pass	Fail
1	XY31PC003	20000	PCS	100%	0%	20000	0
2	XY31PC003	20000	PCS	100%	0%	20000	0
3	XY31PC003	20000	PCS	100%	0%	20000	0
4	XY31PC003	20000	PCS	100%	0%	20000	0
5	XY31PC003	20000	PCS	100%	0%	20000	0
6	XY31PC003	20000	PCS	100%	0%	20000	0
7	XY31PC003	20000	PCS	100%	0%	20000	0
8	XY31PC003	20000	PCS	100%	0%	20000	0
9	XY31PC003	20000	PCS	100%	0%	20000	0
10	XY31PC003	20000	PCS	100%	0%	20000	0
11	XY31PC003	20000	PCS	100%	0%	20000	0
12	XY31PC003	20000	PCS	100%	0%	20000	0
13	XY31PC003	20000	PCS	100%	0%	20000	0
14	XY31PC003	20000	PCS	100%	0%	20000	0
15	XY31PC003	20000	PCS	100%	0%	20000	0
16	XY31PC003	20000	PCS	100%	0%	20000	0
17	XY31PC003	20000	PCS	100%	0%	20000	0
18	XY31PC003	20000	PCS	100%	0%	20000	0
19	XY31PC003	20000	PCS	100%	0%	20000	0
20	XY31PC003	20000	PCS	100%	0%	20000	0
21	XY31PC003	20000	PCS	100%	0%	20000	0
22	XY31PC003	20000	PCS	100%	0%	20000	0
23	XY31PC003	20000	PCS	100%	0%	20000	0
24	XY31PC003	20000	PCS	100%	0%	20000	0
25	XY31PC003	20000	PCS	100%	0%	20000	0
26	XY31PC003	20000	PCS	100%	0%	20000	0
27	XY31PC003	20000	PCS	100%	0%	20000	0
28	XY31PC003	20000	PCS	100%	0%	20000	0
29	XY31PC003	20000	PCS	100%	0%	20000	0
30	XY31PC003	20000	PCS	100%	0%	20000	0
31	XY31PC003	20000	PCS	100%	0%	20000	0
32	XY31PC003	20000	PCS	100%	0%	20000	0
33	XY31PC003	20000	PCS	100%	0%	20000	0
34	XY31PC003	20000	PCS	100%	0%	20000	0
35	XY31PC003	20000	PCS	100%	0%	20000	0
36	XY31PC003	20000	PCS	100%	0%	20000	0
37	XY31PC003	20000	PCS	100%	0%	20000	0
38	XY31PC003	20000	PCS	100%	0%	20000	0
39	XY31PC003	20000	PCS	100%	0%	20000	0
40	XY31PC003	20000	PCS	100%	0%	20000	0
41	XY31PC003	20000	PCS	100%	0%	20000	0
42	XY31PC003	20000	PCS	100%	0%	20000	0
43	XY31PC003	20000	PCS	100%	0%	20000	0
44	XY31PC003	20000	PCS	100%	0%	20000	0
45	XY31PC003	20000	PCS	100%	0%	20000	0
46	XY31PC003	20000	PCS	100%	0%	20000	0
47	XY31PC003	20000	PCS	100%	0%	20000	0
48	XY31PC003	20000	PCS	100%	0%	20000	0
49	XY31PC003	20000	PCS	100%	0%	20000	0
50	XY31PC003	20000	PCS	100%	0%	20000	0
51	XY31PC003	20000	PCS	100%	0%	20000	0
52	XY31PC003	20000	PCS	100%	0%	20000	0
53	XY31PC003	20000	PCS	100%	0%	20000	0
54	XY31PC003	20000	PCS	100%	0%	20000	0
55	XY31PC003	20000	PCS	100%	0%	20000	0
56	XY31PC003	20000	PCS	100%	0%	20000	0
57	XY31PC003	20000	PCS	100%	0%	20000	0
58	XY31PC003	20000	PCS	100%	0%	20000	0
59	XY31PC003	20000	PCS	100%	0%	20000	0
60	XY31PC003	20000	PCS	100%	0%	20000	0
61	XY31PC003	20000	PCS	100%	0%	20000	0
62	XY31PC003	20000	PCS	100%	0%	20000	0
63	XY31PC003	20000	PCS	100%	0%	20000	0
64	XY31PC003	20000	PCS	100%	0%	20000	0
65	XY31PC003	20000	PCS	100%	0%	20000	0
66	XY31PC003	20000	PCS	100%	0%	20000	0
67	XY31PC003	20000	PCS	100%	0%	20000	0
68	XY31PC003	20000	PCS	100%	0%	20000	0
69	XY31PC003	20000	PCS	100%	0%	20000	0
70	XY31PC003	20000	PCS	100%	0%	20000	0
71	XY31PC003	20000	PCS	100%	0%	20000	0
72	XY31PC003	20000	PCS	100%	0%	20000	0
73	XY31PC003	20000	PCS	100%	0%	20000	0
74	XY31PC003	20000	PCS	100%	0%	20000	0
75	XY31PC003	20000	PCS	100%	0%	20000	0
76	XY31PC003	20000	PCS	100%	0%	20000	0
77	XY31PC003	20000	PCS	100%	0%	20000	0
78	XY31PC003	20000	PCS	100%	0%	20000	0
79	XY31PC003	20000	PCS	100%	0%	20000	0
80	XY31PC003	20000	PCS	100%	0%	20000	0
81	XY31PC003	20000	PCS	100%	0%	20000	0
82	XY31PC003	20000	PCS	100%	0%	20000	0
83	XY31PC003	20000	PCS	100%	0%	20000	0
84	XY31PC003	20000	PCS	100%	0%	20000	0
85	XY31PC003	20000	PCS	100%	0%	20000	0
86	XY31PC003	20000	PCS	100%	0%	20000	0
87	XY31PC003	20000	PCS	100%	0%	20000	0
88	XY31PC003	20000	PCS	100%	0%	20000	0
89	XY31PC003	20000	PCS	100%	0%	20000	0
90	XY31PC003	20000	PCS	100%	0%	20000	0
91	XY31PC003	20000	PCS	100%	0%	20000	0
92	XY31PC003	20000	PCS	100%	0%	20000	0
93	XY31PC003	20000	PCS	100%	0%	20000	0
94	XY31PC003	20000	PCS	100%	0%	20000	0
95	XY31PC003	20000	PCS	100%	0%	20000	0
96	XY31PC003	20000	PCS	100%	0%	20000	0
97	XY31PC003	20000	PCS	100%	0%	20000	0
98	XY31PC003	20000	PCS	100%	0%	20000	0
99	XY31PC003	20000	PCS	100%	0%	20000	0
100	XY31PC003	20000	PCS	100%	0%	20000	0

6. report

[illegible]

Safety is our serious job for our worker and engineer team

