

Inspection Report

Report No.: XYN-130822

Supplier : XY-GLOBAL

Inspection Date:14th Sep-, 2013

Inspector:LEO

Inspection only for: PO . XYN-130822 Item No.1402310	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402310	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	品名 品名CNC品名品名品名品名品名CNC品名
品名	品名AL6061 AL6065品名AL6063品名AL7075品名&NBSP; SUS304品名SUS303品名SUS316品名品名
品名	品名品名品名
品名	品名品名 品名品名品名品名品名品名
品名	品名品名品名
品名	CNC品名品名品名品名品名品名品名品名品名品名品名
品名	品名品名gague品名品名 品名品名品名品名品名品名品名品名品名品名品名品名品名 品名
品名	品名
品名/品名	+/-0.01品名
品名	T / T 50品名品名50品名T / T品名品名
品名	品名品名品名品名品名品名品名品名品名品名品名品名品名 品名
品名	品名品名品名品名品名品名品名品名品名品名品名 品名
品名	品名
品名	T / T 50品名品名20-25 NBSP
品名	品名品名
1.Name品名 cnc品名	
2.Process品名品名品名	
品名品名AL6061 AL6065品名AL6063品名AL7075品名品名	
4.品名品名品名品名品名品名品名 品名	
5.Tolerance品名±0.01品名	
6.品名品名100品名	
7.Specification品名serice品名品名品名	
8.品名品名25-30品名品名品名	
9.品名品名品名品名品名品名 品名accessoried品名品名品名	
10.品名品名品名品名Austrial品名品名	
11&NBSP;品名ISO 9001	
品名 品名	
1.品名10品名品名ISO品名	
2.品名品名品名	
3.品名品名品名kindls品名available	
4.品名品名品名品名品名	
5.品名品名品名	
6.品名品名	
7.品名品名品名品名品名	
品名 品名	
品名品名&NBSP;品名品名品名品名	
品名品名品名品名品名	
品名品名品名品名ISO9001	
品名品名品名品名品名品名品名	
品名品名品名品名	