

Inspection Report

Report No.: XYBA-141124
Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-141124 Item No. XY21ZC042	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC042	5000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

Item	Spec	Actual	Unit	Pass	Fail	Remark
1	10.00	10.00	mm	100	0	
2	10.00	10.00	mm	100	0	
3	10.00	10.00	mm	100	0	
4	10.00	10.00	mm	100	0	
5	10.00	10.00	mm	100	0	
6	10.00	10.00	mm	100	0	
7	10.00	10.00	mm	100	0	
8	10.00	10.00	mm	100	0	
9	10.00	10.00	mm	100	0	
10	10.00	10.00	mm	100	0	
11	10.00	10.00	mm	100	0	
12	10.00	10.00	mm	100	0	
13	10.00	10.00	mm	100	0	
14	10.00	10.00	mm	100	0	
15	10.00	10.00	mm	100	0	
16	10.00	10.00	mm	100	0	
17	10.00	10.00	mm	100	0	
18	10.00	10.00	mm	100	0	
19	10.00	10.00	mm	100	0	
20	10.00	10.00	mm	100	0	
21	10.00	10.00	mm	100	0	
22	10.00	10.00	mm	100	0	
23	10.00	10.00	mm	100	0	
24	10.00	10.00	mm	100	0	
25	10.00	10.00	mm	100	0	
26	10.00	10.00	mm	100	0	
27	10.00	10.00	mm	100	0	
28	10.00	10.00	mm	100	0	
29	10.00	10.00	mm	100	0	
30	10.00	10.00	mm	100	0	
31	10.00	10.00	mm	100	0	
32	10.00	10.00	mm	100	0	
33	10.00	10.00	mm	100	0	
34	10.00	10.00	mm	100	0	
35	10.00	10.00	mm	100	0	
36	10.00	10.00	mm	100	0	
37	10.00	10.00	mm	100	0	
38	10.00	10.00	mm	100	0	
39	10.00	10.00	mm	100	0	
40	10.00	10.00	mm	100	0	
41	10.00	10.00	mm	100	0	
42	10.00	10.00	mm	100	0	
43	10.00	10.00	mm	100	0	
44	10.00	10.00	mm	100	0	
45	10.00	10.00	mm	100	0	
46	10.00	10.00	mm	100	0	
47	10.00	10.00	mm	100	0	
48	10.00	10.00	mm	100	0	
49	10.00	10.00	mm	100	0	
50	10.00	10.00	mm	100	0	
51	10.00	10.00	mm	100	0	
52	10.00	10.00	mm	100	0	
53	10.00	10.00	mm	100	0	
54	10.00	10.00	mm	100	0	
55	10.00	10.00	mm	100	0	
56	10.00	10.00	mm	100	0	
57	10.00	10.00	mm	100	0	
58	10.00	10.00	mm	100	0	
59	10.00	10.00	mm	100	0	
60	10.00	10.00	mm	100	0	
61	10.00	10.00	mm	100	0	
62	10.00	10.00	mm	100	0	
63	10.00	10.00	mm	100	0	
64	10.00	10.00	mm	100	0	
65	10.00	10.00	mm	100	0	
66	10.00	10.00	mm	100	0	
67	10.00	10.00	mm	100	0	
68	10.00	10.00	mm	100	0	
69	10.00	10.00	mm	100	0	
70	10.00	10.00	mm	100	0	
71	10.00	10.00	mm	100	0	
72	10.00	10.00	mm	100	0	
73	10.00	10.00	mm	100	0	
74	10.00	10.00	mm	100	0	
75	10.00	10.00	mm	100	0	
76	10.00	10.00	mm	100	0	
77	10.00	10.00	mm	100	0	
78	10.00	10.00	mm	100	0	
79	10.00	10.00	mm	100	0	
80	10.00	10.00	mm	100	0	
81	10.00	10.00	mm	100	0	
82	10.00	10.00	mm	100	0	
83	10.00	10.00	mm	100	0	
84	10.00	10.00	mm	100	0	
85	10.00	10.00	mm	100	0	
86	10.00	10.00	mm	100	0	
87	10.00	10.00	mm	100	0	
88	10.00	10.00	mm	100	0	
89	10.00	10.00	mm	100	0	
90	10.00	10.00	mm	100	0	
91	10.00	10.00	mm	100	0	
92	10.00	10.00	mm	100	0	
93	10.00	10.00	mm	100	0	
94	10.00	10.00	mm	100	0	
95	10.00	10.00	mm	100	0	
96	10.00	10.00	mm	100	0	
97	10.00	10.00	mm	100	0	
98	10.00	10.00	mm	100	0	
99	10.00	10.00	mm	100	0	
100	10.00	10.00	mm	100	0	

6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	0.5kg
尺寸	100mm x 100mm x 10mm
公差	±0.01mm
表面处理	阳极氧化
包装	纸箱
交货期	10天
备注	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10 □□□□□ISO□□

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

[illegible]

--	--	--	--	--

[illegible]

□□□□□□□□ ISO9001

[illegible]

OEM					
-----	--	--	--	--	--