

Inspection Report

Report No.: XYK-131011
Supplier : XY-GLOBAL

Inspection Date: 29th Oct-, 2013
Inspector: LEO

Inspection only for: PO . XYK-131011 Item No. Aluminum alloy bolt	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Aluminum alloy bolt	3000SET	5% inspection	0pcs	No failure	3000SET

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 5% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

品名	鋼板 CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075&NBSP; SUS304SUS303SUS316
厚さ	1mm
寸法	1000mm x 1000mm
表面処理	研磨仕上げ
公差	CNC加工品±0.01mm
検査方法	目視検査、ゲージ検査、重量測定
梱包方法	木箱包装
単位	枚
公差	+/-0.01mm
仕様	T / T 50mmT / T 50mm
備考	※ご注文の際は、必ず仕様書をご確認ください。
品質保証	品質保証書発行可能
納期	約1週間
送料	T / T 50mm20-25 NBSP
お問い合わせ先	営業部
1.Name 鋼板 CNC加工品	
2.Process 機械加工	
3.材料 AL6061 AL6065AL6063AL7075	
4.用途 機械部品、構造物	
5.Tolerance ±0.01mm	
6.重量 100kg	
7.Specification 仕様書参照	
8.保管期間 25-30年	
9.付属品 加工済みの部品、accessories	
10.認証 ISO9001 Austria	
11.&NBSP; ISO 9001	
お問い合わせ先	
1. 10mm ISO	
2. 10mm	
3. kinds available	
4. 10mm	
5. 10mm	
6. 10mm	
7. 10mm	
お問い合わせ先	
&NBSP;	
お問い合わせ先	
ISO9001	
お問い合わせ先	
お問い合わせ先	