

Inspection Report


Report No.: XYBA-140921
Supplier : XY-GLOBAL

Inspection Date:18th Oct-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-140921 Item No. XY21ZC014	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC014	1000PCS	7% inspection	0pcs	No failure	1000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化 喷砂 抛光
包装	泡沫箱+气泡膜+木架
交货期	15天
付款方式	预付30% 货到付70%
备注	50mm 25mm
其他	

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

--	--	--	--	--

1.10 10000 ISO

2.

3. □□□□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6. □□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
