

Inspection Date: 5th Apr, 2015
Inspector: Leo

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY012	18000PCS	1% inspection	0pcs	No failure	18000pcs

No failure.

Dimension Inspection:

No failure , below measurement report for reference

Assembly Test:

No failure	
------------	--

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. report

[illegible]