

Inspection Report

Report No.: XYDW-140627
Supplier: XY-GLOBAL

Inspection Date: 22th July, 2014
Inspector: Leo

Inspection only for: PO : XYDW-140627 Item No. XY33AH020	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY33AH020	90000PCS	1% inspection	0pcs	No failure	90000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product



3. Product



4 Product

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Customer: XY-GLOBAL	Product Name: XY33AH020	Inspection Date: 2014.07.22	Inspector: Leo
Part No: XY33AH020	Lot No: XY33AH020	Quantity: 90000	Unit: PCS
1. Scope: This inspection is performed on the product XY33AH020, which is a metal component used in the assembly of the XY33AH020 product. 2. Purpose: The purpose of this inspection is to verify that the product meets the requirements specified in the drawing and the inspection plan. 3. Method: The inspection is performed using a visual inspection method. 4. Result: The inspection result is that the product meets the requirements. 5. Conclusion: The product is acceptable for use.			

5. Product:

6. report

[illegible]