

## Inspection Report

**Supplier : XY-GLOBAL**

**Inspector: Leo**

|                                                                |                                   |
|----------------------------------------------------------------|-----------------------------------|
| Inspection only for:<br>PO . XYDW-140622    Item No. XY33AH015 | <u>Inspection Result:</u><br>PASS |
|----------------------------------------------------------------|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY33AH015   | 32000PCS      | 1% inspection | 0pcs         | No failure          | 32000pcs        |

**Appearance Inspection :**

No failure.

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

## Inspection Summary

The inspection sample plan is 100% inspection.

## Digital photo records :



### 1. Packing



## 2. Product



### 3. Product



## 4 Product

[illegible]

## 5. Product:

## 6. report

[illegible]