

Inspection Report

Report No.: XYBA-140903
Supplier : XY-GLOBAL

Inspection Date: 1st Oct., 2014
Inspector: LEO

Inspection only for: PO : XYBA-140903 Item No. XY21ZC002	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC002	1200PCS	7% inspection	0pcs	No failure	1200pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product:

3. Product:

4. Product:

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Document No.	XY-21ZC002	Revision	1.0	Inspection Date	2014.10.01
Part Name	XY21ZC002	Material	Aluminum	Inspector	LEO
Quantity	1200	Unit	PCS	Customer	XY-GLOBAL

Inspection Method: 100% Inspection

Inspection Result: PASS

Inspector: LEO

Company: XY Electronics Technology Co., Ltd

Item	Check Item	Check Result	Check Date	Check By
1	Material	OK	2014.10.01	LEO
2	Dimension	OK	2014.10.01	LEO
3	Surface	OK	2014.10.01	LEO
4	Position	OK	2014.10.01	LEO
5	Quantity	OK	2014.10.01	LEO
6	Label	OK	2014.10.01	LEO
7	Storage	OK	2014.10.01	LEO
8	Transportation	OK	2014.10.01	LEO
9	Usage	OK	2014.10.01	LEO
10	Disposal	OK	2014.10.01	LEO
11	Recycling	OK	2014.10.01	LEO
12	Other	OK	2014.10.01	LEO

5. Product :

6. Inspection report:

11

品名	铝合金CNC加工零件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
公差	±0.01mm
表面处理	阳极氧化
包装	纸箱
交货期	15天
备注	请提供详细图纸

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100 [illegible]

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11□□□□□□□□ISO 9001

[illegible]

1.10 10000 ISO 100

2. □□□□□□□□□□□□□□

3. □□□□□□□□□□□□

4. □□□□□□□□

5.□□□□□

6.□□□□□□

7.

Page 10

[illegible]

□□□□□□□□□□ISO9001

[illegible]

OEM
