

Inspection Report

Report No.: XYAN-150313

Supplier : XY-GLOBAL

Inspection Date: 16th Apr-, 2015

Inspector:LEO

Inspection only for: PO . XYBA-150313 Item No. XY21ZC100	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC100	12000pcs	7% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

[illegible]

6. Inspection report:

品名	汎用部品CNC加工品汎用部品CNC加工品
材質	材質 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
仕様	仕様
数量	数量
単位	単位
公差	公差
表面処理	表面処理
検査方法	検査方法
納入期	納入期
保管場所	保管場所
梱包方法	梱包方法
備考	備考
1. 汎用部品CNC加工品	
2. 汎用部品CNC加工品	
汎用部品AL6061 AL6065AL6063AL7075	
4. 汎用部品CNC加工品 公差	
5. 汎用部品±0.01mm	
6. 汎用部品100mm	
7. 汎用部品CNC加工品	
8. 汎用部品25-30mm	
9. 汎用部品CNC加工品 公差	
10. 汎用部品CNC加工品	
11. 汎用部品ISO 9001	
汎用部品	
1.10 汎用部品ISO	
2. 汎用部品CNC加工品	
3. 汎用部品CNC加工品	
4. 汎用部品CNC加工品	
5. 汎用部品	
6. 汎用部品	
7. 汎用部品CNC加工品	
汎用部品	
汎用部品CNC加工品	
汎用部品CNC加工品	
汎用部品ISO9001	
汎用部品CNC加工品	
汎用OEM加工品	

Safety is our serious job for our worker and engineer team

