

Inspection Report

Report No.: XYKS-140609
Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
Inspector: Leo

Inspection only for: PO : XYSK-140609 Item No. XY31SY53	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY53	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :

No failure,

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Name	XY31SY53	Product Type	XY31SY53	Inspection Date	2014.07.05
Part No.	XY31SY53	Lot No.	XY31SY53	Inspection Time	14:00:00
Inspector	Leo	Inspector	Leo	Inspector	Leo

Inspection Result: ☒ PASS ☐ FAIL

Inspection Summary: The inspection sample plan is 100% inspection.

Inspection Details:

Item	Inspection Item	Inspection Result	Inspection Time
1	Appearance	PASS	14:00:00
2	Dimension	PASS	14:00:00
3	Assembly	PASS	14:00:00
4	Function	PASS	14:00:00
5	Reliability	PASS	14:00:00
6	Stability	PASS	14:00:00
7	Consistency	PASS	14:00:00
8	Repeatability	PASS	14:00:00
9	Accuracy	PASS	14:00:00
10	Precision	PASS	14:00:00
11	Resolution	PASS	14:00:00
12	Linearity	PASS	14:00:00
13	Proportionality	PASS	14:00:00
14	Monotonicity	PASS	14:00:00
15	Continuity	PASS	14:00:00
16	Stability	PASS	14:00:00
17	Repeatability	PASS	14:00:00
18	Accuracy	PASS	14:00:00
19	Precision	PASS	14:00:00
20	Resolution	PASS	14:00:00

Inspector: Leo

5. Product:

6. report

	CNC
	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
	+/-0.01
	5050
	5025
1.CNC	
2.	
AL6061 AL6065AL6063AL7075	
4.	
5.± 0.01	
6.100	
7.	
8.25-30	
9.	
10.	
11ISO 9001	
1.10ISO	
2.	
3.	
4.	
5.	
6.	
7.	
ISO9001	
OEM	

Safety is our serious job for our worker and engineer team

