

Inspection Report

Report No.: XYSA-130518

Supplier : XY-GLOBAL

Inspection Date: 15th Jun, 2013

Inspector: Leo

Inspection only for: PO . XYSA-130518 Item No. XY11SL024	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL024	8000PCS	5% inspection	0pcs	No failure	8000pcs

Appearance Inspection :

No failure.

Dimension Inspection:

No failure , below measurement report for reference.

Assembly Test:

No failure

Inspection Summary

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product

[illegible]

5. Product:

6. The test report

項目	項目詳細説明項目詳細説明項目詳細説明OEM項目詳細説明
項目	項目ADC12項目A380項目
項目	項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明
項目/項目	+/-0.01項目
項目	項目50項目項目項目項目項目50項目
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明
項目	項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目
項目	項目
項目	項目50項目項目25項目
項目	項目詳細説明項目詳細説明
1.項目項目詳細説明	
2.項目項目詳細説明項目詳細説明項目	
3.項目項目ADC12項目A380項目	
4.項目詳細説明項目詳細説明項目詳細説明項目	
5.項目項目±0.01項目	
6.項目項目100項目	
7.項目詳細説明項目詳細説明項目詳細説明項目	
8.項目項目25-30項目	
9.項目詳細説明項目詳細説明項目詳細説明項目詳細説明項目	
10.項目詳細説明項目詳細説明項目詳細説明項目	
11.項目項目ISO 9001	
項目	
1.10項目項目ISO項目	
2.項目詳細説明項目詳細説明項目	
3.項目詳細説明項目詳細説明項目	
4.項目詳細説明項目	
5.項目	
6.項目	
7.項目詳細説明項目	
項目	
項目詳細説明項目詳細説明項目	
項目詳細説明項目	
項目項目ISO9001	
項目詳細説明項目詳細説明項目	
項目OEM項目詳細説明	

Safety is our serious job for our worker and engineer team

